



00057779310

TRANSPORT ORDER

00057779310

RNM-EC-4038595



DATE: 15/05/2026

CONSIGNOR (name, address, country) MERCEDES-BENZ AG TRANSPORTLOGISTIK AM MITTELKAI 57 - DE-70327 STUTTGART-WANGEN TEL: VAT ID NR DE 321281763 REF: 40122724		FEATURES ☐ Time Slot pick-up ☐ Time Slot delivery ☐ Tail Lift pick-up ☐ Tail Lift delivery ☐ Under Customs ☐ Fixed Delivery Date ☐ Pre-Advise Delivery ☐ Pre-12 Delivery ☐ Pre-10 Delivery ☐ Double deck		ORIGIN TERMINAL (name, address, country) RNM - DHL FREIGHT GMBH INDUSTRIESTRASSE 28 DE-71272 RENNINGEN TEL: FAX: E-MAIL:	
COLLECTION ADDRESS MERCEDES-BENZ AG RHENUSHALLE 29 / AM MITTELKAI 5 - 7 DE-70327 STUTTGART		TRANSPORT INSURANCE ☐ Yes ☒ No VALUE CURRENCY		DESTINATION TERMINAL (name, address, country) BRI - DHL GLOBAL FORWARDING (ITALY) SPA VIA DEI GLADIOLI, 18 IT-70026 MODUGNO TEL: FAX: E-MAIL:	
CONSIGNEE (name, address, country) MAGNA B.V. & CO. KG VIA DEI CICLAMINI 4 IT-70026 MODUGNO TEL: VAT ID NR REF: 10195925		INCO TERMS CODE PRODUCT CODE DAP ECI EKAER SENT UIT Code:			
DELIVERY ADDRESS MAGNA B.V. & CO. KG VIA DEI CICLAMINI 4 IT-70026 MODUGNO					
QUANTITY & GOODS DESCRIPTION 1 CT - CARTON / PACKAGE - 7DCT300 Ge			GROSS WEIGHT 80.0 kg	m3 / LDM 0.336 m3	LWH (Cm) 80/60/70
DELIVERY TERMS DELIVERED AT PLACE		COD GOODS	COD FREIGHT	TOTAL VALUE	TOTAL GROSS WEIGHT 80.0 kg
TOTAL m3 / LDM 0.336 m3					
DANGEROUS GOODS INFORMATION					
INSTRUCTIONS			Loading Equipment Exchange		
COLLECTION AT CONSIGNOR DATE: TIME:		IMPORTANT INFORMATION According to CMR, transport damages have to be noted on the transport order (POD) upon delivery of the consignment. Damages not visible externally should be notified in writing to the responsible EUROCONNECT terminal within 7 days of delivery.		DELIVERY TO CONSIGNEE DATE:	
STAMP & SIGNATURE OF CONSIGNOR		STAMP & SIGNATURE OF CONSIGNEE Via del Cielo 10 - 70026 Modugno (BA) MISSION 2050 ZERO EMISSIONS GREEN 19 MAG 2026 "Ricevuto con riserva di verifica su qualità e quantità"			
DRIVER'S SIGNATURE		CONSIGNEE'S NAME (in block letters)			

Transport conditions apply exclusively to all consignments (www.logistics.dhl/freight).



Mercedes-Benz

Quality Engineering Center

Datum: 11.05.2026
Abteilung: MO/QCX
Ansprechpartner: Clemens Kunz
Telefon: +49 71117 56381
E-Mail: star.kunz@extaccount.com
Hauspostcode: --

Verantwortlicher: Alexandre Muller
Telefon: +49 711 17-32255

Ersteller: Stephanie Löffler
Lieferantennummer: 16722084
Lieferantenr. Versand: 16722084E

Mercedes-Benz AG --

Magna PT B.V. & Co. KG
Hermann-Hagenmeyer-Straße
74199 Untergruppenbach

Magna PT B.V. & Co. KG
Via dei Ciclamini 4
70026 Modugno BA



AF000072610001

Feldprüfbericht

Prüfberichtsnummer: A F 726100.1

Items listed below have been removed from customer vehicles by the Mercedes-Benz Service Organization due to different malfunctions. In order to get the failure cause clarified we ask you for a quick investigation of reclaimed parts. We urgently demand that you improve your quality situation and eliminate the cause(s) of errors through the prompt implementation of targeted measures. Further we need a detailed analysis report, which identifies the exact root cause of failure for every part. To guarantee the future prevention of failures, caused by supplier, we require 8D reports with initiated and accomplished activities. We need your statements via QEC-Tool in the Supplier-Portal at: <https://supplier.mercedes-benz.com>. Please, note the deadline shown in the portal after the parts are received. In case the requested information is not received in the appropriate time, all undocumented parts will be considered as accepted concerning recovery acceptance rates. Parts with failures outside your responsibility and that are marked as "vendor return required" have to be sent back to Mercedes-Benz AG, Abl.ST. 541, in den Weiden 29, DE 73776 Altbach, Germany within 14 calendar days after your statement date. Likewise, parts not sent in time (receiving date Mercedes-Benz) will also be considered as accepted. The returned parts must be labeled with the QEC-Tool barcode label. Otherwise they will be considered as accepted. Parts with failures outside your responsibility and that are not marked as "vendor return required" have to be stored for at least 10 weeks. If Mercedes-Benz AG is requesting those parts they have to be returned to Mercedes-Benz AG (address: see above). All analysis must be performed according to "MBN 10448 Schadteilanalyse Feld". You will find this standard in the DocMaster within the supplier portal: <https://supplier.mercedes-benz.com>.

Sachnummer	Benennung	Anzahl
Referenznummer	Entscheidungscode	
Beanstandung		

A7003704000	7DCT300 Getriebe Benzin	1
202600453	S4 RCS	
TIPS-FallNr.: 86716758. BA: Fzg. brems sehr stark. beim Rückwärtsfahren. 20. Vermutlich Klappen. di Schaltgabel für den Rückwärtsgang. Getriebe hängt momentan im Rückwärtsgang. (BA)		

MO/QCX

i.V. Alm

**Ricevuto con riserva di
verifica su qualità e quantità**
i.V. Cognigni
Seite 1 von 1