



Sk darf bech

DOCUMENTO DI TRASPORTO (D.d.t.)

D.P.R. 472 del 14.08.1996 - D.P.R. 696 del 21.12.1996

Cedente

**Magna PT S.p.A.
Via dei Ciclamini 4
I-70026 MODUGNO**

Partita iva: IT04886850728

Numero: **40002703**
Data: **12.12.2022**
Documento materiale: **5012366087**
Ordine di acquisto: **5500038855**

Creato da: **ANTOMOSC**

Destinatario

**Schaeffler Technologies AG & C
Georg-Schäfer-Strasse 30
D-97421 SCHWEINFURT
GERMANIA**

Partita iva:

Luogo di destinazione

**Schaeffler Technologies AG & C
Georg-Schäfer-Strasse 30
D-97421 SCHWEINFURT
GERMANIA**

Partita iva:

922	EM ord. acq. Storno	Trasporto a mezzo vettore
------------	----------------------------	----------------------------------

Posizione	Quantità	U.M.	Codice materiale	Descrizione materiale	Peso netto	U.M.
001	3.842	PZ	9000112873	Ralla interna cuscinetto	576,300	KG

305675

Aspetto		Nota	
PEDANE		I.R.2-118200	
Colli	Peso lordo	Tipo trasporto	ID Trasporto
4 PZ	984,000 KG		
Vettore		Data e ora del ritiro	Firma
FLASH		16.12.2022 10:06:17	
			Conducente
			Destinatario



Quality Inspection Report

Inspection report No.: 200000118200
 Receipt No.: 5012339280
 Deliver note: 22991153

Date of inspection: 12.12.2022
 Date of reception: 28.11.2022

Supplier

Schaeffler Technologies AG & Co. KG
 Georg-Schäfer-Strasse 30
 97421 Schweinfurt
 Germany

Quality Contact

Name: Ruggero Doronzo
 Phone:
 E-Mail: Ruggero.Doronzo@magna.com

Material

Material-No.: 9000112873
 Description: Tapered Roller Bearing Inner Ring

Delivery Qty: 11520
 Tax ID number: DE291636029

Preliminary information for Supplier:

While inspecting your delivery we have identified the below mentioned quality demerits.
 We would like to request you to take according containment actions and to avoid repetitive failures in future.
 In case we identify further issues within our receiving or production processes we inform you with an additional inspection report.

The payment of the goods after identification of the demerit does not automatically apply as acceptance of the goods.

We expect your reply to this inspection report (e.g. 8D) addressed to below contact until

Failure description:

Dragtorque G7 M in analog 40C

Dragtorque G7 M in analog 40C only to send back the parts

Quantity Affected: 3,842 Parts

We expect a written response within 24h concerning your immediate containment actions.

Please send your containment actions in form of a 8D report to

following email: getrag.hotline.supplier@magna.com

Please only use the specific MAGNA Supply Chain Management templates which you can receive from your contact or at GETRAG.SMRT@magna.com

In regards to potential cost chargebacks our regress department U/CRG will get in contact with you.

Affected Quantity:

Claimed quantity: 3842
 Redelivered quantity: 3842

Best regards

MOV. 5012366087

Ruggero Doronzo

Magna PT S.p.A.
 a socio unico
 Via dei Ciclamini 4
 I-70026 Modugno (Bari)
 Tel. 080 - 5 85 81 11
 Fax. 080 - 5 85 82 04
 Subject to the activity of the direction
 and coordination of
 Magna Powertrain GmbH

Cap.Soc.: EUR 25.850.000,00
 i.v.R. Imprese di Bari
 C.F. e P.IVA 04886850728
 REA 339886
 www.magna.com

EUR: BNL-Banca Nazionale del
 Lavoro SpA
 IBAN code EUR: IT94 V010 0504 0000
 0000 0007 855
 BIC code: BNLITRR 6560 12
 USD: Bank of America N.A.
 IBAN code USD: GB64 BOFA 1650
 5071 1710 20
 BIC code: BOFAGB22

*Ritiro a
 cura del
 fornitore*

4 ~~peol.~~ peol. 984,2 kg